

Fire Extinguisher and Electrical Panel Inspection

In order to keep the insurance rate and coverage that we currently hold, every unit in the community must have a Fire Extinguisher which needs to be inspected, serviced and tagged annually. (Model 2A10BC was the one recommended).

You can purchase a new extinguisher at any supplier of your choice. Should you decide to service your existing fire extinguisher you may contact Triangle Fire at (305) 592-3011. They are located in Doral.

Additionally, it is important to inspect the electrical panels and clean the exhaust/vents of the clothes dryers in order to avoid issues and potential damage based on findings by other owners.

If you have any questions or need further assistance, please contact our office by email at colony@doralmanagement.com or by phone at (305) 591-8715.